# Volvo Penta

# MD2030B Piston Kit Question

Hello,

I have a customer with a MD2030B who purchased a Standard Piston kit part #876694. Can we confirm that the new piston is supposed to have the flat surface because it is clearly different from the old piston. Please see attached pic.

Thanks,

**********

Hello,

the answer from Volvo's engineering department is that yes, the piston is correct.

Thanks,

**********

Unique solution ID: #1124
Author:
Last update: 2015-03-05 18:14



**(c) 2024 <bsutter@marinepartsexpress.com> | 2024-03-29 14:35**

URL: http://faq.marinepartsexpress.com/index.php?action=artikel&cat=3&id=125&artlang=en