

PCM

I am looking for fuel control cell part #R089004 for my PCM engine, do you have any in stock?

According to PCM, the only solution they can offer is a complete new RA080031 plus an additional fitting R024163 to replace the R089004.

Attached is a quote for the replacements which are available.

I was unable to find you anyone who has one of the original R089004s in stock.

Unique solution ID: #1262

Author: Dan Bettencourt

Last update: 2020-07-13 13:28