

Mercruiser

Mercury 4954200RX Pump Question

Hello Sir:

This pump 4954200RX is a rebuilt pump remanufactured by Cummins and comes with a one year warranty.

The RX is a Rebuild Exchange which means that there is a core charge of \$875 on the pump. The core charge is to encourage customers to return their old pumps so that Cummins can rebuild them. The core charge is reimbursed to you once I receive your old pump here at Marine Parts Express. Once we receive the old pump we will credit your card the \$875.

We have this pump in stock and can ship it out, but I wanted to be sure that you understood the extra core charge before we ran your card. Please let me know.

J. D. Neeson
President

Unique solution ID: #1093

Author:

Last update: 2015-03-03 19:53