## Volvo Penta Volvo Part 854934 Now 21389074 Question

Hello Sir:

Attached is a diagram of the upper unit of the sail drive. Ref. 70 is the big rubber seal that is squeezed between the upper and lower units that seals the sail drive to the hull from the inside.
The number for this kit, on the diagram, is 854934 which includes the seal and some other gaskets Actually Volvo Penta superceedes this number to 21389074 which is the new kit number.
Most times we replace both, but the 21389074 is expensive (around \$432.).
J.D.  **********************************
Unique solution ID: #1144 Author: Last update: 2015-03-10 14:35